

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AB160
WSW
1/4-1/2
0.291 mi.
1535 ft.

SPEEDWAY GAS STATION 7829
1620 NEPTUNE AVE
BROOKLYN, NY

Site 4 of 5 in cluster AB

NY Spills **S121463581**
N/A

Relative:
Higher

Actual:
3 ft.

SPILLS:

Name: SPEEDWAY GAS STATION 7829
Address: 1620 NEPTUNE AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1709221 / 2018-01-31
Facility ID: 1709221
Facility Type: ER
DER Facility ID: 519146
Site ID: 565662
DEC Region: 2
Spill Cause: Traffic Accident
Spill Class: C4
SWIS: 2401
Spill Date: 2018-01-08
Investigator: PXLAKHAN
Referred To: Not reported

Reported to Dept: 2018-01-08
CID: Not reported
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2018-01-08
Spill Record Last Update: 2018-01-31
Spiller Name: Not reported
Spiller Company: CUSTOMER
Spiller Address: Not reported
Spiller Company: 999
Contact Name: MIKE MATRI
DEC Memo: "01/12/18 - Lakhani 2 gallons of gasoline spilled to the concrete gas station pad. A car hit the gas pump and ruptured a line. FDNY responded and laid absorbent onto the concrete. Contained to the concrete. Pumps are out of service. Speedway technician was soon to be arriving to the site. According to the gas station manager, the gasoline has been cleaned up. Sandeep (territory manager) can be contacted at 732-540-5631. 01/31/18 - Lakhani EnviroTrac Edward Russo (O: 631-924-3001, C: 516-523-6714, edr@envirotrac.com) submitted a closure report for the spill at the Speedway Gas Station #7829. Spill Closure Request (EnviroTrac, 01/29/18) - On 01/08/18, dispenser #2 was hit by a vehicle at the site, which caused a gasoline spill of an unknown quantity. Station personnel spread speedy dry to cleanup the surface. EnviroTrac spread additional speedy dry, swept the site, and placed the impacted speedy dry into ten (1) 55-gallon drums. The spill was contained within the concrete surface of the station and it appeared that there was impact to soil or groundwater. on 01/19/18, the drums were picked up and properly disposed of. Spill is closed."

Remarks: "Car hit gas pump and ruptured supply line. FD responded and contained and cleanup crew is enroute."

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

All Materials:

Site ID:	565662
Operable Unit ID:	1313599
Operable Unit:	01
Material ID:	2321067
Material Code:	0009
Material Name:	gasoline
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	2.00
Units:	G
Recovered:	Not reported
Oxygenate:	Not reported